


## A new rotator for the 3cm antenna

As we had some problems with the indicator from our old system we decided to replace the old rotator to a new one. Below there are some pictures from our job.



*Abbildung 1: DJ2NR is doing a hard job*



*Abbildung 2: Thomas DC1NNN is a great help...*







*Abbildung 4: DL6NAA on top of the tower*



*Abbildung 3: ...fixing the new rotator*



*Abbildung 5: the complete 3cm system ready to lift*



*Abbildung 6: a simple crane lifts the 250Kg easy...*








*Abbildung 7: DL6NAA is fixing the cables*





*Abbildung 8: complete system ready to work*

*Abbildung 9: the new indicator*



*Abbildung 11: DK5NI celebrates the new rotator with a small steak...*



*Abbildung 10: Frank DL9NDA has finished his job....*

